HS-421 Accelerometer

4-20mA velocity and AC acceleration output via M12 Connector


Key Features


- Unique output
- · For use with PLC/DCS systems and data collectors
- · Customizable features

Industries

Building services, Pulp and Paper, Mining, Metals, Utilities, Automotive, Water, Pharmaceutical







Pin 3

No Connection

Connection Details

°é 0

Technical Performance

Mounted Base Resonanc	e 5kHz min
Velocity Ranges	see: 'How To Order' table ±10%
	Nominal 80Hz at 72°F
Frequency Response	600cpm (10Hz) to 60kcpm (1kHz) ± 5% - ISO10816
Isolation	Base isolated
Range	see: 'How To Order' table
Transverse Sensitivity	Less than 5%

Case Material	
Sensing Element/Constru	
Mounting Torque	

Mechanical

2.


ction Mounting Torque Weight Sheilded Cable Assembly Mounting Threads

Stainless Steel PZT/Compression 5.9ft. lbs 5.2 oz. (nominal) HS-AC010 - straight HS-AC011 - right angle see: 'How To Order' table

Electrical

Outputs	4-20mA DC current proportional to
	Range and AC acceleration
Bias Voltage	3 Volts DC (nominal)
Supply Voltage	15-30 Volts DC (for 4-20mA)
Settling Time	2 seconds
Output Impedance	Loop Resistance 600 Ohms max. at 24 Volts
Case Isolation	>10 ⁸ Ohms at 500 Volts

Typical Frequency Response



Environmental

Operating Temperature Range Sealing Maximum Shock EMC

-13 to 194°F
IP67
5000g
EN61326-1:2013


Applications

Fans, Motors, Pumps, Compressors, Centrifuges, Conveyors, Air Handlers, Gearboxes, Rolls, Dryers, Presses, Cooling, VAC, Spindles, Machine Tooling, Process Equipment

Vibration sensor should be firmly fixed to a flat surface (spot face surface may be needed to be produced and cable anchored to sensor body.)



How To Order





www.hansfordsensors.com sales@hansfordsensors.com



We reserve the right to alter the specification of this product without prior notice TS030U.4