



For use with accelerometers with quick-fit threads.

Mounting Studs provide a secure, permanent or semi-permanent point of connection

Part No.	Connection Point 1	Connection Point 2	
HS-AS001	Quick Fit Male	Glue Face	
HS-AS002	Quick Fit Male	M8 Male	
HS-AS003	Quick Fit Male	M6 Male	
HS-AS004	Quick Fit Male	1⁄4"-28 UNF Male	
HS-AS007	Quick Fit Male	M10 Male	
HS-AS010	Quick Fit Male	M8 x 1.25 Female	
HS-AS011	Quick Fit Male	M6 x 1 Female	
			3
HS-AS012	Quick Fit Male	1⁄4"-28 UNF Female	
HS-AS013	Quick Fit Male (9/16" UNC)	Glue Face	
HS-AS018	Quick Fit Male (1/2" UNC)	Glue Face	



www.hansfordsensors.com sales@hansfordsensors.com

CE

X

We reserve the right to alter the specification of this product without prior notice  $$\mathsf{TS100U.4}$$ 

## HS-AS Studs Quick Fit threads

Part No.

Connection Point 1 Connection Point 2

HS-AS033	Quick Fit Male	M8 x 1 Male		
HS-AS034	Quick Fit Male (½" UNC)	M6 x 1 Male		
HS-AS037	Quick Fit Male (½" UNC)	M8 x 1.25 Male		
HS-AS041	Quick Fit Male	3/8" BSP	2	
HS-AS049	Quick Fit Male	1/8" BSP		
113-A3049		170 BSF		
HS-AS064	Quick Fit Male	M5 Male	×.	Sec. 1
HS-AS065	Quick Fit Male	Glue face and M6 x 1 Female		٢
HS-AS072	Quick Fit Male	M8 x 8mm Male	ę	٩
HS-AS078	Quick Fit Male	Glue Face in 316L Stainless Steel		
HS-AS108	Quick Fit Male	M12 Male		
HS-AS120	Quick Fit Male	1/4"NPT Male	P	



www.hansfordsensors.com sales@hansfordsensors.com

We reserve the right to alter the specification of this product without prior notice TS100U.4

