## HS-AS Studs mounting/grub screws





Screw studs for use to adapt a female thread into a male thread.

Mounting Studs provide a secure, permanent or semi-permanent point of connection

Part No.	Connection Point 1	Connection Point 2		
HS-AS008	1/4"-28 UNF Male	M8 Male		
HS-AS020	10-32 UNF 3/8" Male	10-32 UNF 3/8" Male		
HS-AS021	1/4"-28 UNF Male	M10 Male	8	
N3-A3021	/4 -20 UNF Wale	WITO Wate		
HS-AS022	1/4"-28 UNF 1/2" Male	1/4"-28 UNF 1/2" Male		
HS-AS023	1/4"-28 UNF Male	M8 Male		
HS-AS024	1/4"-28 UNF Male	M6 Male		
HS-AS025	1/4"-28 UNF Male	3/8"-24 UNF Male		
	7,4 <b>20 0</b> 111 maio	oro 1. c. ii iii ii i		
110 40040	1/2 00 HNE M.L.	40.00 UNE M. I	<u></u>	
HS-AS043	1/4"-28 UNF Male	10-32 UNF Male		
			8	
HS-AS053	1/4"-28 UNF Male	M6 Male		
HS-AS066	1/4"-28 UNF Male	M6 Male	MATION AND AND AND AND AND AND AND AND AND AN	
HS-AS067	1/4"-28 UNF Male	M8 Male	The same	Comp. (i)
HS-AS068	1/4"-28 UNF Male	M10 Male		
110-70000	74 -20 OINI IVIAIC	IN TO MIGIC		







## HS-AS Studs mounting/grub screws

				(
Part No.	Connection Point 1	Connection Point 2		
HS-AS069	1/4"-28 UNF Male	1/4"-28 UNF Male		
HS-AS076	½"-28 UNF Male	M6 Male		
HS-AS081	1/4"-28 UNF Male	M12 Male		
LIC ACORS	1/" OO HINE Mala	M10 Male		
HS-AS083	1⁄4"-28 UNF Male	MTO Male		
HS-AS084	1/4"-28 UNF Male	M5 Male		
HS-AS086	1/4"-28 UNF Male	M8 x 1 Male		
HS-AS090	1/4"-28 UNF Male	M10 x 1.25 Male		
HS-AS101	1/4"-28 UNF Male	½"-28 UNF Male		
HS-AS102	½"-28 UNF Male	½"-28 UNF Male		
ПЗ-АЗ 102	/4 -20 UNF Wale	/2 -20 UNF Wale		
HS-AS104	1/4"-28 UNF Male	M6 Male		
HS-AS110	1/4"-28 UNF Male	M10 x 1.25 Male		
			<b>8</b>	
HS-AS112	1/4"-28 UNF Male	M12 x 1.5 Male		
	4/1 00 1111			
HS-AS115	1/4"-28 UNF Male	1/2" - 13 TPI UNC x 1" Male		
HS-AS122	1/4"-28 UNF Male	M10 x 1 Male		



